DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/30/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED		
		445126	B. WING		08/2	08/27/2012	
	PROVIDER OR SUPPLIER	CHIE	30	EET ADDRESS, CITY, STATE, ZIP COD 50 DELL TRAIL, PO BOX 878 UNLAP, TN 37327	E 		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORI (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE	
K 130 SS=D	Medical gas storage protected in accord Standards for Healt (a) Oxygen storage 3,000 cu.ft. are enc separation. (b) Locations for su 3,000 cu.ft. are vent 4.3.1.1.2, 19.3.2.4 This STANDARD is Based on observatifacility failed to store accordance with NF The finding included Observation on 8/27 unsecured oxygen or room 401 (physical This finding was ack administrator and the during the exit conference of the NFPA 101 MISCELL OTHER LSC DEFICE	locations of greater than losed by a one-hour pply systems of greater than ted to the outside. NFPA 99 one met as evidenced by: ion, it was determined the explanation of the explanation of the path	K 076	 The unsecured oxygen of been removed from the barroom 401. All oxygen cylinders checked to assure they are being an area enclosed by a separation. An inservice will be held we to assure the proper storage of followed. The Director of Maintena designee will check the oxygen a daily basis for two weekly thereafter to assustorage. A report will be given to the Assurance Committee. 	throom of have been ng stored in one hour ofth all staff f oxygen is ance or his gen storage weeks and ore proper	10/14/12	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/30/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED	
		445126	B. WING			08/27/2012	
	PROVIDER OR SUPPLIER			3	REET ADDRESS, CITY, STATE, ZIP CODE 60 DELL TRAIL, PO BOX 878 DUNLAP, TN 37327		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAC	ΊX	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE API DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
	Continued From page 1 This STANDARD is not met as evidenced by: Based on observation, it was determined the facility failed to comply with the life safety code. The finding included: Observation on 8/27/12 at 11:39 AM revealed the fire door by the Director of Nursing office did not close within frame. This finding was acknowledged by the facility administrator and the maintenance director during the exit conference on 8/27/12. NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2		K 130		 The Fire Door by the Director of Nursing's office closes within frame. All Fire Doors have been checked and close within frame. The Fire Door was repaired so it now closes within frame. The Director of Maintenance or his designee will check all fire doors daily and during fire drills to assure they are closing within frame. A report will be given to the Quality Assurance Committee. 		10/14/12
	Based on observatifacility failed to propand equipment. The findings include 1. Observation on 8 storage or equipment panels in the physic 2. Observation on 8 extension cords in use and a power-strip in These findings were administrator and means a stress of the s				 No equipment is being stored in front of the electrical panel in the physical therapy department. No extension cord is being used in the information office. All electrical panels have been checked to assure there is no storage or equipment in front of the panel. All offices and other areas have been checked to assure there are no extension cords in use. 		10/14/12

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/30/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE S COMPL	(X3) DATE SURVEY COMPLETED	
		445406	B. WIN	· · · · · · · · · · · · · · · · · · ·	1		
NAME OF PRO	OVIDER OR SUPPLIER	445126				27/2012	
	THCARE, SEQUA	TCHIE	Ì	STREET ADDRESS, CITY, STATE, ZIP CO 360 DELL TRAIL, PO BOX 878 DUNLAP, TN 37327	DE		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COI (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE	
				3. An inservice will held with emphasize the importance of any items in front of electrical not using extension cords. The electrical panel in the therapy department has been with a sign to keep area clean. 4. The Director of Mainten designee will monitor all elect to assure there is nothing sto of the panel and there is extension cords. A report will be given to Assurance Committee.	f not storing al panels and the physical marked off of items. thance or his trical panels red in front no use of	10/14/12	